

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 1.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-023740**Date Inspected:** 17-May-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 730**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1600**Contractor:** American Bridge/Fluor Enterprises, a JV**Location:** Job Site**CWI Name:** N / A**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** S.A.S. components**Summary of Items Observed:**

The Quality Assurance Inspector (QAI), Scott Croff, was present at the Self Anchored Span (SAS) job site to observe the scheduled fabrication and welding of components for the SFOBB project.

The QAI reviewed contract related documents including the submitted and approved Welding Quality Control Plan (WQCP) and approved revisions to the WQCP. The QAI continued reviewing the informal weekly welding report packages #55 and #56. The QAI was provided with a bootleg copy of weekly welding report #57. The QAI began reviewing the informal documents for conformance with the contract requirements.

The QAI was requested to sample fastener assemblies that have been delivered to the contractor's job site storage area. The QAI met with Caltrans Transportation Engineer Bob Brignano and was provided with the fastener assemblies and the rocap documents. The QAI pulled random samples to satisfy the contract requirements for verification. The QAI assigned lot number B212-016-11 and generated a TL-102 form with the pertinent information. The QAI noted that these fastener assemblies will be delivered to the Translab later this week. See the attached photos.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)



Summary of Conversations:

The QAI relayed the status of document reviews and fastener sampling / testing to the QAI Lead Bill Levell. Except as described above, there were no other notable conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Nina Choy (510) 385-5910, who represents the Office of Structural Materials for your project.

Inspected By: Croff, Scott

Quality Assurance Inspector

Reviewed By: Levell, Bill

QA Reviewer